

Platinum Edition 2-Speed Heavy-Duty Wood Shaper

(Model 43-420)



DATED 9-17-99

PART NO. 432-02-651-0012
©Delta International Machinery Corp. 1999



TABLE OF CONTENTS

SAFETY RULES	3
ADDITIONAL SAFETY RULES FOR SHAPERS	4
UNPACKING AND CLEANING.....	5
ASSEMBLY INSTRUCTIONS	
Assembling Spindle Raising And Lowering Handwheel	8
Assembling Extension Wings To Shaper Table.....	8
Assembling Switch Bracket And On/Off Switch.....	9
Assembling Fence To Shaper Table	10
Assembling Guards To Fence Body.....	12
Assembling And Changing Spindles.....	13
Assembling Table Inserts	14
Assembling Cutters And Collars To Spindle.....	14
Assembling Spindle Guard.....	15
CONNECTING SHAPER TO POWER SOURCE	
Grounding Instructions	16
Single Phase Operation	16
Three Horsepower Motors	16
OPERATING CONTROLS AND ADJUSTMENTS	
Starting And Stopping The Shaper	17
Locking Switch In The “OFF” Position.....	17
Raising And Lowering Spindle.....	18
Changing Speeds And Adjusting Belt Tension	18
Reversing Spindle Rotation.....	18
Fence Controls And Adjustments.....	19
Guard Controls And Adjustments	20
OPERATIONS	
Shaping When Using The Fence As A Guide.....	21
Shaping With Collars And Starting Pin	22
Position Of Collars	22
Starting Pin	23
REPLACING SPINDLE CARTRIDGE	23
ACCESSORIES	24-27
PARTS, SERVICE OR WARRANTY ASSISTANCE	28
WARRANTY.....	28

SAFETY RULES

Woodworking can be dangerous if safe and proper operating procedures are not followed. As with all machinery, there are certain hazards involved with the operation of the product. Using the machine with respect and caution will considerably lessen the possibility of personal injury. However, if normal safety precautions are overlooked or ignored, personal injury to the operator may result. Safety equipment such as guards, push sticks, hold-downs, featherboards, goggles, dust masks and hearing protection can reduce your potential for injury. But even the best guard won't make up for poor judgment, carelessness or inattention. Always use common sense and exercise caution in the workshop. If a procedure feels dangerous, don't try it. Figure out an alternative procedure that feels safer. REMEMBER: Your personal safety is your responsibility.

This machine was designed for certain applications only. Delta Machinery strongly recommends that this machine not be modified and/or used for any application other than that for which it was designed. If you have any questions relative to a particular application, DO NOT use the machine until you have first contacted Delta to determine if it can or should be performed on the product.

DELTA INTERNATIONAL MACHINERY CORP.
MANAGER OF TECHNICAL SERVICES
246 ALPHA DRIVE
PITTSBURGH, PENNSYLVANIA 15238
(IN CANADA: 644 IMPERIAL ROAD, GUELPH, ONTARIO N1H 6M7)

WARNING: FAILURE TO FOLLOW THESE RULES MAY RESULT IN SERIOUS PERSONAL INJURY

1. **FOR YOUR OWN SAFETY, READ INSTRUCTION MANUAL BEFORE OPERATING THE TOOL.** Learn the tool's application and limitations as well as the specific hazards peculiar to it.

2. **KEEP GUARDS IN PLACE** and in working order.

3. **ALWAYS WEAR EYE PROTECTION.**

4. **GROUND ALL TOOLS.** If tool is equipped with three-prong plug, it should be plugged into a three-hole electrical receptacle. If an adapter is used to accommodate a two-prong receptacle, the adapter lug must be attached to a known ground. Never remove the third prong.

5. **REMOVE ADJUSTING KEYS AND WRENCHES.** Form habit of checking to see that keys and adjusting wrenches are removed from tool before turning it "on."

6. **KEEP WORK AREA CLEAN.** Cluttered areas and benches invite accidents.

7. **DON'T USE IN DANGEROUS ENVIRONMENT.** Don't use power tools in damp or wet locations, or expose them to rain. Keep work area well-lighted.

8. **KEEP CHILDREN AND VISITORS AWAY.** All children and visitors should be kept a safe distance from work area.

9. **MAKE WORKSHOP CHILDPROOF** – with padlocks, master switches, or by removing starter keys.

10. **DON'T FORCE TOOL.** It will do the job better and be safer at the rate for which it was designed.

11. **USE RIGHT TOOL.** Don't force tool or attachment to do a job for which it was not designed.

12. **WEAR PROPER APPAREL.** No loose clothing, gloves, neckties, rings, bracelets, or other jewelry to get caught in moving parts. Nonslip footwear is recommended. Wear protective hair covering to contain long hair.

13. **ALWAYS USE SAFETY GLASSES.** Wear safety glasses. Everyday eyeglasses only have impact resistant lenses; they are not safety glasses. Also use face or dust mask if cutting operation is dusty.

14. **SECURE WORK.** Use clamps or a vise to hold work when practical. It's safer than using your hand and frees both hands to operate tool.

15. **DON'T OVERREACH.** Keep proper footing and balance at all times.

16. **MAINTAIN TOOLS IN TOP CONDITION.** Keep tools sharp and clean for best and safest performance. Follow instructions for lubricating and changing accessories.

17. **DISCONNECT TOOLS** before servicing and when changing accessories such as blades, bits, cutters, etc.

18. **USE RECOMMENDED ACCESSORIES.** The use of accessories and attachments not recommended by Delta may cause hazards or risk of injury to persons.

19. **REDUCE THE RISK OF UNINTENTIONAL STARTING.** Make sure switch is in "OFF" position before plugging in power cord.

20. **NEVER STAND ON TOOL.** Serious injury could occur if the tool is tipped or if the cutting tool is accidentally contacted.

21. **CHECK DAMAGED PARTS.** Before further use of the tool, a guard or other part that is damaged should be carefully checked to ensure that it will operate properly and perform its intended function – check for alignment of moving parts, binding of moving parts, breakage of parts, mounting, and any other conditions that may affect its operation. A guard or other part that is damaged should be properly repaired or replaced.

22. **DIRECTION OF FEED.** Feed work into a blade or cutter against the direction of rotation of the blade or cutter only.

23. **NEVER LEAVE TOOL RUNNING UNATTENDED. TURN POWER OFF.** Don't leave tool until it comes to a complete stop.

24. **DRUGS, ALCOHOL, MEDICATION.** Do not operate tool while under the influence of drugs, alcohol or any medication.

25. **MAKE SURE TOOL IS DISCONNECTED FROM POWER SUPPLY** while motor is being mounted, connected or re-connected.

26. **WARNING:** The dust generated by certain woods and wood products can be injurious to your health. Always operate machinery in well ventilated areas and provide for proper dust removal. Use wood dust collection systems whenever possible.

ADDITIONAL SAFETY RULES FOR WOOD SHAPERS

1. **WARNING: DO NOT OPERATE YOUR WOOD SHAPER UNTIL IT IS COMPLETELY ASSEMBLED AND INSTALLED ACCORDING TO THE INSTRUCTIONS.**

2. **IF YOU ARE NOT** thoroughly familiar with the operation of Wood Shapers, obtain advice from your supervisor, instructor or other qualified person.

3. **MAKE SURE** wiring codes and recommended electrical connections are followed and that machine is properly grounded.

4. **NEVER** turn the shaper "ON" before clearing the table of all objects (tools, scraps of wood, etc.).

5. **DO NOT** process materials less than 12 in length or 4 in width without special supporting fixtures. Use push sticks, featherboards or holddowns whenever possible.

6. **ALWAYS** use a miter gage and clamp attachment when edge shaping work less than 6 wide. The fence should be removed during this operation.

7. **AVOID** awkward hand positions where a sudden slip could allow your hand to contact the cutter.

8. **KEEP** hands away from cutting tool.

9. **NEVER** run the stock between the fence and the cutter.

10. **DO NOT** feed material that is warped, contains knots or is embedded with foreign objects, such as nails or staples.

11. **NEVER** start the shaper with the stock in contact with the cutter.

12. **NEVER** reach under the table while the machine is running.

13. **NEVER** perform layout, assembly or set-up work on the table while the shaper is operating.

14. **KEEP** cutters sharp and free from rust and pitch.

15. **THE FENCE** halves should be adjusted so that the cutter opening is never more than is required to clear the cutter.

16. **ALWAYS** lock fence hardware after making fence adjustments.

17. **MAKE CERTAIN** cutters are properly secured before starting machine.

18. **DO NOT** perform any operation freehand. **ALWAYS** use fence for straight shaping; miter gage for edge shaping; and starting pin and rub collars for curve shaping.

19. **ALWAYS** keep front motor access panel closed while operating shaper.

20. **ALWAYS** feed against the cutter rotation, as shown in Fig. A.




Fig. A

21. **WHEN SHAPING** with collars and starting pin, the collar **MUST** have sufficient bearing surface, as shown in Fig. B. Fig. C, illustrates the wrong way for this operation as the collar **DOES NOT** have sufficient bearing surface.




Fig. B




Fig. C

22. **WHEN SHAPING** with collars and starting pin, the work must be fairly heavy in proportion to the cut being made as shown in Fig. D. **UNDER NO CIRCUMSTANCES** should short work of light body be shaped against the collars as shown in Fig. E.




Fig. D




Fig. E

ADDITIONAL SAFETY RULES FOR WOOD SHAPERS

(continued)

23. **WHEN SHAPING** with collars and starting pin, the cutter should be positioned below the collar whenever possible, as shown in Fig. F.




Fig. F

24. **MAKE** all adjustments with the power "OFF".

25. **KEEP** guard in place at all times.

26. **BEFORE** leaving the machine, make sure the work area is clean.

27. **SHOULD** any part of your shaper be missing, damaged or fail in any way, or any electrical component fail to perform properly, shut off switch and remove plug from power supply outlet. Replace missing, damaged or failed parts before resuming operation.

28. **ADDITIONAL INFORMATION** regarding the safe and proper operation of this product is available from the National Safety Council, 1121 Spring Lake Drive, Itasca, IL 60143-3201, in the Accident Prevention Manual for Industrial Operations and also in the Safety Data Sheets provided by the NSC. Please also refer to the American National Standards Institute ANSI 01.1 Safety Requirements for Woodworking Machinery and the U.S. Department of Labor OSHA 1912.213 Regulations.

29. **SAVE THESE INSTRUCTIONS.** Refer to them often and use them to instruct others.

UNPACKING AND CLEANING

Carefully unpack the shaper and fence system from the shipping containers. Clean all loose parts and remove the protective coating from the machined surfaces of the shaper table. This coating may be removed with a soft cloth moistened with kerosene (do not use acetone, gasoline, or lacquer thinner for this purpose). Figures 2 and 3, illustrate the shaper and all loose items supplied with the machine. Fig. 4, illustrates the items supplied with the fence system.



Fig. 2




Fig. 3

- | | |
|--|---|
| 4. 10 Wide Cast Iron Extension Wings | 17. Keyed Washer |
| 5. Wrenches (2) | 18. Spindle |
| 6. 7/16-20 x 1 Hex Cap Screws (6) for mounting extension wings | 19. Tie Rod |
| 7. Flat Washers (6) for mounting extension wings | 20. Tie Rod Nut |
| 8. Handwheel | 21. Keps Nut (2) for mounting switch-to-switch mounting bracket |
| 9. Key for Handwheel | 22. Phillips Head Screw (2) for mounting switch-to-switch mounting bracket |
| 10. Lock Knob | 23. Flange Nut (4) for mounting switch mounting bracket to shaper |
| 11. Guard | 24. Truss Head Machine Screw (4) for mounting switch mounting bracket to shaper |
| 12. 3/4 I.D. Washer (2) | 25. Switch Adapter Plate (2) for mounting switch mounting bracket to shaper |
| 13. 3/4 I.D. x 1/2 Thick Collar | 26. Starting Pin |
| 14. 3/4 I.D. x 3/4 Thick Collar | |
| 15. 3/4 I.D. x 1 Thick Collar | |
| 16. Spindle Nut | |




Fig. 4

- | | |
|---|---|
| 27. Fence Body | 37. Hex Soc. Hd. Screw (4) for mounting guard mounting bracket to top cover |
| 28. Left and Right fence halves | 38. Rod for fence guard |
| 29. Locking Levers (2) for fence halves | 39. Holddown for fence guard |
| 30. Flat Washers (2) for locking levers | 40. Brackets for fence guard (4) |
| 31. Spring clamp for fence guard | 41. Flat washers (2) for mounting top cover to fence body |
| 32. Top cover | 42. Lock Knobs (2) for mounting top cover to fence body |
| 33. Guard Mounting Bracket | 43. Flat Washers (2) for fence locking handles |
| 34. Clear Plastic Guard | 44. Fence Locking Handles (2) for mounting fence to shaper |
| 35. Hex Nuts (4) for mounting guard mounting bracket to top cover | 45. Lock Bars (23) for fence halves |
| 36. Lock Washers (8) for mounting guard mounting bracket to top cover | |

ASSEMBLY INSTRUCTIONS

WARNING: FOR YOUR OWN SAFETY, DO NOT CONNECT THE SHAPER TO THE POWER SOURCE UNTIL THE SHAPER IS COMPLETELY ASSEMBLED AND YOU HAVE READ AND UNDERSTOOD THE ENTIRE INSTRUCTION MANUAL.

ASSEMBLING SPINDLE RAISING AND LOWERING HANDWHEEL

1. Insert key (A) Fig. 5, into slot in spindle raising and lowering shaft (B) as shown.
2. Assemble handwheel (C) Fig. 5, onto spindle shaft (B), making certain the key (A) fits into the slot (D) in the handwheel. Insert the set screw which holds the handwheel to the shaft and tighten screw firmly against key.
3. Thread lock knob (E) Fig. 6, into the spindle shaft (B).




Fig. 5



Fig. 6

ASSEMBLING EXTENSION WINGS TO SHAPER TABLE

1. Assemble extension wing (A) Fig. 7, to shaper table (B) using three 1-1/4 inch-long hex head screws (C) and flat washers (D) supplied. Use a straight edge (E) Fig. 7, to make certain the extension wing is level with shaper table before tightening three screws (C). Assemble and level remaining extension wing in the same manner.
2. Fig. 8, illustrates both extension wings assembled to shaper table.




Fig. 7



Fig. 8




Fig. 9




Fig. 10

ASSEMBLING SWITCH BRACKET AND ON/OFF SWITCH

1. The on/off switch (A) Fig. 9, and switch mounting bracket (B) are shipped inside the shaper cabinet. Open the side door of the shaper cabinet, remove switch package and remove packaging material.

2. Position switch mounting bracket (B) Fig. 10, so holes (C) are over hole (D) in shaper cabinet (E), then fasten bracket (B) to cabinet (E) using four truss head screws (F) Fig. 9, flange nuts (G) and two switch adapter plates (H). **NOTE: Switch adapter plates (H) are to be positioned inside the shaper cabinet as shown in Fig. 11.**

3. Fig. 12, illustrates switch mounting bracket (B) properly mounted to shaper cabinet.

4. Assemble on/off switch (A) Fig. 9, to switch mounting bracket (B) Fig. 12, through two holes (J), using two Phillips head screws (K) Fig. 9, and Keps nuts (L).

5. Fig. 13, illustrates on/off switch properly mounted to switch mounting bracket.




Fig. 11




Fig. 12



Fig. 13

ASSEMBLING FENCE TO SHAPER TABLE

1. The fence on this shaper can be mounted parallel to the miter gage slot using two holes (B) Fig. 14, or 90 degrees to the miter slot by using two holes (A). The following illustrates mounting the fence parallel to the miter gage.

2. Place fence body (C) Fig. 15, on the table as shown, and locate the two fence locking levers with washers (D) and fence lock bars (E).




Fig. 14




Fig. 15




Fig. 16

3. Fasten bar (E) to the front of the fence half using the locking lever and washers (D), as shown in Figs. 16 and 17. Assemble the remaining bar to the other fence half in the same manner. **NOTE: Locking levers (D) are spring-loaded and can be repositioned by pulling out the handle and repositioning it on the nut located underneath the hub of the handle.**




Fig. 17

4. Locate the two fence locking handles and washers, one of which is shown at (F) Fig. 18, and fasten fence body (C) to one of the set of holes located on the shaper table illustrated in Fig. 14.




Fig. 18

5. Fig. 19, illustrates fence body (C) fastened to the table with the two fence locking handles (F).




Fig. 19

6. Loosen locking lever (D) Fig. 20, and slide rear of fence half (G) onto locking bar (E). Assemble remaining fence half in the same manner. Then tighten locking lever (D) to secure each fence half to the fence body.




Fig. 20

7. Assemble guard mounting bracket (H) Fig. 21, to top cover (J) using the four inch-long hex head cap screws, hex nuts, and eight lock washers (K) as shown in Fig. 22.

8. Assemble top cover (J) Fig. 22, to top of fence body (C) using the two locking knobs and washers (L).

9. Fig. 23, illustrates top cover properly assembled to the fence body.




Fig. 21




Fig. 22




Fig. 23

ASSEMBLING GUARDS TO FENCE BODY

1. Assemble guard bracket (A) Fig. 24, and hex rod (B) to upright hex shaft (C) as shown.




Fig. 24

2. Assemble two guard brackets (A) Fig. 25, and clear plastic guard (D) to holddown (E) as shown.




Fig. 25

3. Assemble holddown/clear plastic guard assembly to hex rod (B) as shown in Fig. 26.

4. Assemble guard bracket (A) Fig. 27, and spring clamp (F) to hex rod (B) as shown, then tighten all wing nuts.

5. The spring guard (F), holddown (E) and clear plastic guard (D) can be flipped up out of the way as shown in Fig. 28, by lifting up on locking lever (G), when not in use or when making adjustments. **CAUTION: When the guard assembly is in the down position as shown in Fig. 27, make certain locking lever (G) is in the locked position as shown.**




Fig. 26




Fig. 27




Fig. 28

6. Fig. 29, illustrates complete fence and guard assembly mounted in the alternate position, 90 degrees to miter gage slot.




Fig. 29

ASSEMBLING AND CHANGING SPINDLES

MAKE CERTAIN THE MACHINE IS DISCONNECTED FROM THE POWER SOURCE.

1. Thread one end of the tie rod (A) Fig. 30, into the threaded hole in the bottom of the spindle (B).




Fig. 30

2. Insert tie rod and spindle into the spindle cartridge, making sure the pin (C) Fig. 31, in the spindle cartridge, is engaged with notch (D), in the spindle.

3. Fig. 32, illustrates the spindle (B), inserted into the spindle cartridge.

4. Thread nut (E) Figs. 30 and 33, onto bottom end of tie rod (A).

5. Place wrench on flats (F) Fig. 32, on top of spindle and tighten nut (E) Fig. 33, on bottom of tie rod to fasten spindle to spindle cartridge.




Fig. 31




Fig. 32




Fig. 33

ASSEMBLING TABLE INSERTS

Three table inserts are provided for various size cutters, as shown in Fig. 34. The large insert is adjustable and should be set flush with the table as follows:

1. Remove the three slotted head screws (A) Fig. 34.
2. Using a screwdriver, turn the three adjusting screws (B) Fig. 34, until insert is flush with table. Then replace the slotted head screws (A).




Fig. 34

ASSEMBLING CUTTERS AND COLLARS TO SPINDLE

1. There are three different sized collars (A) Fig. 35, supplied with the shaper. These collars will allow the cutter and/or the 4-1/2 diameter spindle guard to be positioned at various locations on the spindle.
2. When assembling cutters to the spindle, it is suggested that the cutter be positioned as close to the bottom of the spindle as possible. This will reduce the possibility of spindle run-out, which may effect the finished appearance of the cut.




Fig. 35

3. After determining if any collars are needed, assemble cutter (B) Fig. 35, keyed washer (C), and spindle nut (D) as shown in Fig. 36, then place one wrench on flats (E) on top of spindle and one wrench on spindle nut (D) and tighten as shown in Fig. 37.
4. **IMPORTANT:** Always place “keyed” washer (C) Fig. 36, on spindle before screwing on nut (D). The “keyed” washer (C) prevents the nut (D), from loosening when spindle turns counterclockwise.




Fig. 36



Fig. 37

ASSEMBLING SPINDLE GUARD

A 4-1/2" diameter spindle guard is supplied as standard equipment and is supplied with a 1/2" bushing which enables the guard to be used with both the 1/2" and 3/4" spindles.

CAUTION: The diameter of the spindle guard should be at least 1" more than the maximum cutting circle of the shaper cutter and the height of the guard should not exceed 1/4" above the material.

To assemble the spindle guard, proceed as follows:

MAKE CERTAIN THE MACHINE IS DISCONNECTED FROM THE POWER SOURCE.

1. Two 1/2" I.D. and two 3/4" I.D. washers are supplied with the 4-1/2" diameter spindle guard to accommodate 1/2" and 3/4" spindles. These washers are to be positioned directly above and below the spindle guard. Place one of the washers (A) on the spindle, over either the cutter or collar, as shown in Fig. 38.




Fig. 38

2. Place the spindle guard (B) Fig. 39, on the spindle, then place the other washer (C) and "keyed" washer (D) on the spindle as shown.




Fig. 39

3. Thread spindle nut (E) Fig. 40, onto spindle, then place one wrench on flats on top of spindle and one wrench on spindle nut (E) and tighten as shown.

4. **IMPORTANT:** Always place "keyed" washer (D) Fig. 39, on spindle before screwing on spindle nut (E) Fig. 40. The "keyed" washer (D) Fig. 39, prevents the spindle nut (E) Fig. 40, from loosening when the spindle turns counterclockwise.



Fig. 40

CONNECTING SHAPER TO POWER SOURCE

GROUNDING INSTRUCTIONS

CAUTION: THIS TOOL MUST BE GROUNDED WHILE IN USE TO PROTECT THE OPERATOR FROM ELECTRIC SHOCK.

In the event of a malfunction or breakdown, grounding provides a path of least resistance for electric current to reduce the risk of electric shock. The motor is equipped with an electric cord having an equipment-grounding conductor and a grounding plug. The plug must be plugged into a matching outlet that is properly installed and grounded in accordance with all local codes and ordinances.

Do not modify the plug provided - if it will not fit the outlet, have the proper outlet installed by a qualified electrician.

Improper connection of the equipment-grounding conductor can result in risk of electric shock. The conductor with insulation having an outer surface that is green with or without yellow stripes is the equipment-grounding conductor. If repair or replacement of the electric cord or plug is necessary, do not connect the equipment grounding conductor to a live terminal.

Check with a qualified electrician or service personnel if the grounding instructions are not completely understood, or if in doubt as to whether the tool is properly grounded.

Repair or replace damaged or worn cord immediately.

SINGLE PHASE OPERATION

THREE HORSEPOWER MOTORS

The motor supplied with single phase, 3 horsepower Shapers is designed to be operated from a 220-240 volt power system.

The single phase Shaper is intended to be used on a circuit that has an electrical outlet that looks like the one illustrated in Fig. 41. The tool has a plug similar to the plug illustrated in Fig. 41. Make certain the tool is connected to an outlet having the same configuration as the plug. No adapter is available, or should be used with the tool. **CAUTION: IN ALL CASES, MAKE CERTAIN THE RECEPTACLE IN QUESTION IS PROPERLY GROUNDED. IF YOU ARE NOT SURE, HAVE A CERTIFIED ELECTRICIAN CHECK THE RECEPTACLE.**

The single phase, three horsepower Shaper motors are single voltage motors and cannot be connected to operate at a voltage other than 220-240 volts.

If you desire to operate the single phase 3 horsepower Shaper with an extension cord, use a proper extension cord and make certain it is in good condition. When using an extension cord, be sure to use one heavy enough to carry the current your product will draw. An undersized cord will cause a drop in line voltage resulting in loss of power and overheating. Fig. 42, shows the correct size to use depending on cord length and nameplate ampere rating. If in doubt, use the next heavier gage. The smaller the gage number, the heavier the cord.




Fig. 41

TOTAL LENGTH OF CORD IN FEET	GAGE OF EXTENSION CORD TO USE
50	14 AWG
100	12 AWG
Over 100	Not recommended

Fig. 42

OPERATING CONTROLS AND ADJUSTMENTS



Fig. 43

STARTING AND STOPPING THE SHAPER

To apply power to the machine, push “ON” button (A) Fig. 43. To stop the machine, push “OFF” button (B).




Fig. 44

LOCKING SWITCH IN THE “OFF” POSITION

IMPORTANT: We suggest that when the shaper is not in use, the switch be locked in the “OFF” position using a padlock (C) Fig. 44 , through the switch plate and “ON” button as shown.

RAISING AND LOWERING SPINDLE

The spindle can be raised or lowered by loosening lock knob (A) Fig. 45, and turning handwheel (B). To raise the spindle height, turn the handwheel (B) clockwise. To lower the spindle height, turn handle (B) counterclockwise.

The scale (C) Fig. 45, indicates the spindle travel range from 0 to 3 and is marked in 1/16 increments. Minor cutter height adjustments can be measured using the pointer (D) along the scale (C). **CAUTION:** Always tighten lock knob (A) after adjusting spindle height.

CHANGING SPEEDS AND ADJUSTING BELT TENSION

The shaper is supplied with a 2-step motor pulley and a 2-step spindle pulley that provides spindle speeds of 7,000 and 10,000 R.P.M. When the belt is on the largest step of the motor pulley and the smallest step of the spindle pulley, the spindle speed will be 10,000 R.P.M. When the belt is on the smallest step of the motor pulley and the largest step of the spindle pulley, the spindle speed will be 7,000 R.P.M.

A chart (Y) Fig. 46, illustrating the correct belt placement for 7,000 or 10,000 R.P.M. is located on the inside panel of the motor access door.

To change speeds and adjust belt tension, proceed as follows:

1. **DISCONNECT THE MACHINE FROM THE POWER SOURCE** and open motor access door, as shown in Fig. 46.
2. Loosen thumb screw lock (A) Fig. 47. Release tension on belt by moving lever (B), to the left. Position belt (C), on the desired steps of the spindle pulley (D), and the motor pulley (E), and apply belt tension by moving lever (B), to the right. When desired belt tension is applied to belt, retighten thumb screw lock (A).

3. Proper belt tension is attained when there is approximately 3/32 deflection using light finger pressure (approx. 3.5 lbs.) at the center of the belt span between pulleys (D) and (E) Fig. 47. **IMPORTANT:** Pulleys (D) and (E) should always be aligned with each other to provide maximum belt performance and reduce belt wear. To check pulley alignment, refer to section “**REPLACING SPINDLE CARTRIDGE.**”

REVERSING SPINDLE ROTATION

MAKE CERTAIN THE MACHINE IS DISCONNECTED FROM THE POWER SOURCE.

The motor is equipped with a reversing switch (X) Fig. 46, which is located on the motor junction box. **CAUTION:** Never attempt to reverse the rotation of the spindle with the motor running.




Fig. 45




Fig. 46




Fig. 47

FENCE CONTROLS AND ADJUSTMENTS




Fig. 48

1. **DISCONNECT SHAPER FROM POWER SOURCE. IMPORTANT:** The fence halves (A) Fig. 48, should be adjusted endwise so the opening at the spindle is never more than is required to clear the cutter.
2. To adjust the fence halves (A) Fig. 48 endwise, loosen the two fence locking levers (B), slide the fence halves to the required positions, and tighten locking levers (B).
3. Each fence half (A) Fig. 48, can be moved independently, forward or backward, depending on the type of shaping operation that is being performed. To move the fence halves in or out, loosen one of the lock knobs (C) and turn one of the adjusting knobs (D), depending on which fence half is being moved. Turn knob (D) until the correct setting is obtained and tighten lock knob (C).
4. The complete fence assembly can be rapidly positioned on the table by loosening two clamp handles (E) Fig. 48, moving the fence assembly to the desired position, and tightening the two clamp handles (E).
5. Indicator collars (F) Fig. 49, are supplied to give the exact dimension each fence half is moved.
6. Using a straight edge (G) Fig. 50, check to see if the two fence halves (H) are parallel to each other. If parallelism cannot be achieved by adjusting one of the two fence halves (H) in or out, shims (J) Fig. 51, can be placed between the fence (H) and fence mount (K).




Fig. 49




Fig. 50




Fig. 51

GUARD CONTROLS AND ADJUSTMENTS

DISCONNECT SHAPER FROM POWER SOURCE.

The spring clamp (A) Fig. 52, holddown (B), and clear plastic guard (C) are fully adjustable to provide safe protection for most applications. **NOTE: For certain applications, the supplied spindle guard may have to be used or a custom guard may need to be fabricated.**

1. Using a square (not shown), check to see if shaft (D) Fig. 52, on spring clamp (A) is 90 degrees to the table surface. If an adjustment is necessary, proceed as follows:

Lift up on guard locking handle (E) Fig. 53, loosen lock nut (F) and turn screw (G) until shaft (D) is 90 degrees to the table surface; then tighten lock nut (F).

Push down on guard locking handle (E) Figs. 53 and 54, until it locks in place as shown in Fig. 54. If the locking action is too loose or tight, loosen screw (H) and adjust cam washer (J), then tighten screw (H). Repeat this adjustment on the screw and cam washer located on the other side of guard locking handle (E).

2. Adjust holddown (B) Fig. 55, by placing a piece of material which will be used on the table as shown. Loosen thumb screws on guard mounting bracket (K) and adjust holddown (B) over top of workpiece to provide some downward pressure and tighten thumb screws.

3. Adjust clear plastic guard (L) Fig. 55, by loosening thumb screws on guard mounting bracket (M) and locating the guard so it will deflect the wood chips and provide protection from reaching the cutter; then retighten thumb screws.




Fig. 52




Fig. 53




Fig. 54




Fig. 55

4. Loosen thumb screws on guard mounting bracket (P) Fig. 56, and adjust spring clamp (N) so it will provide inward pressure on workpiece; then tighten thumb screws. **NOTE: Thumb screws on guard mounting bracket (R) Fig. 56, can be loosened to permit extension of guard assembly.**

WARNING: TURN THE CUTTER BY HAND TO MAKE CERTAIN CUTTER DOES NOT CONTACT ANY OF THE GUARDING OR FENCE HALVES BEFORE CONNECTING THE SHAPER TO POWER SOURCE.

CAUTION: Always make certain guard locking handle (E) Fig. 56, is in the locked position as shown and all thumb screws are tight on guard assembly before turning shaper on.




Fig. 56

OPERATIONS

The following is an example of the setting up and operational procedures when using the fence, collars, and starting pin. Please review this information carefully before turning on the power to avoid damage to the machine or personal injury.

SHAPING WHEN USING THE FENCE AS A GUIDE

Using the fence is the safest and most satisfactory method of shaping, and this method should always be used when the work permits. Almost all straight work can be shaped using the fence as follows:

1. For average work, where a portion of the original edge of the work is not touched by the cutter, both the front and rear fences are in a straight line, as shown in Fig. 57.




Fig. 57

2. When the shaping operation removes the entire edge of the work, e.g., in jointing or making a full bead, the shaped edge will not be supported by the rear fence when both fences are in line, as shown in Fig. 58. In this case, the work should be advanced to the position shown in Fig. 58, and stopped.




Fig. 58

3. The rear fence should then be advanced to contact the work, as shown in Fig. 59. The rear fence will then be in line with the cutting circle.




Fig. 59

SHAPING WITH COLLARS AND STARTING PIN

When shaping with collars and starting pin, the following rules must always be followed for good work and safety in operation.

1. Collars **MUST** be smooth and free of all gum or other substances.
2. The edge of the work to be shaped **MUST** be smooth, as any irregularity in the surface which rides against the collar will be duplicated on the moulded surface.
3. A portion of the edge of the work **MUST** remain untouched by the cutters in order that the collar will have sufficient bearing surface. Fig. 60, illustrates the **wrong way** for the operation, while Fig. 61 illustrates the **right way**.




Fig. 60




Fig. 61




Fig. 62




Fig. 63

4. The work **MUST** be fairly heavy in proportion to the cut being made as shown in Fig. 62. Under **NO** circumstances should short work of light body be shaped against the collars as shown in Fig. 63.

5. When shaping with collars and starting pin, the Safe Guard II spindle guard, supplied with your machine, should always be used.

POSITION OF COLLARS

1. The collars may be used in any of the following positions: above, below or between two cutters.
2. When the collar is used below the cutter, a shown in Fig. 64, the progress of the cut can be observed at all times. However, any accidental lifting of the work will gouge the wood and ruin the workpiece.
3. When the collar is used above the cutter as shown in Fig. 65, the cut cannot be seen, yet this method offers some advantage in that the cut is not affected by slight variations in the thickness of the stock. Also, accidental lifting of the work will not gouge the workpiece. Simply correct the mistake by repeating the operation.
4. The collar between cutters method, as shown in Fig. 66, has both the advantages of the first two methods and is frequently used where both edges of the work are to be shaped.




Fig. 64




Fig. 65




Fig. 66




Fig. 67



Fig. 68

STARTING PIN

1. Your machine is supplied with a tapered starting pin (A) Fig. 67, which is used as a support when starting the cut. The starting pin (A) is placed on one of the tapered holes (B) in the table.

2. Fig. 68, illustrates starting pin (A) placed into hole in table.

3. The work should be placed in the first position using the guide pin as a support, as shown in Fig. 69. Then swing the work into the cutter as shown in the second position. The work will now be supported by the collar and starting pin as shown in Fig. 69.

4. After the cut has been started, the work is swung free of the starting pin and rides only against the collar as shown in the third position Fig. 70. **ALWAYS FEED AGAINST THE ROTATION OF THE CUTTER.**

IMPORTANT: If the work would be advanced to the cutter without the side support of the starting pin, it would invariably be kicked back.




Fig. 69




Fig. 70

REPLACING SPINDLE CARTRIDGE

1. **IMPORTANT:** When replacing the spindle cartridge, bolt (A) Fig. 71, should only be tightened 7 to 10 foot pounds.

2. The spindle pulley (D) Fig. 72, and motor pulley (E), should always be aligned with each other to provide maximum belt performance to reduce belt wear. To check pulley alignment, place a straight edge against the underside of, and spanning both pulleys, as shown in Fig. 72. If an adjustment is necessary, loosen set screw (F) and move the motor up or down until the two pulleys (D) and (E) are aligned.

3. Proper belt tension is attained when there is approximately 3/32" deflection using light finger pressure (approx. 3.5 lbs.) at the center of the belt span between pulleys (D) and (E) Fig. 72.




Fig. 71





Fig. 72

Delta Shaper Accessories

High-Speed Steel 3-Lip Shaper Cutters

All have 1/2 spindle hole. Involute relief design permits honing of the face without changing the shape. Cutters 09-128 & 09-137 are counter-bored to fit Stub Spindle. Cutters are shown 3/8 size. 1/2 Lb. each.



Straight Cutters—1/2 Hole

Cat. No.	Thick-ness	Dia.	Cat. No.	Thick-ness	Dia.
09-107	1/2	1 1/8	09-105	1 1/2	1 1/8
09-130	3/4	1 1/8	09-108	1/4	1 15/16
09-104	1	1 1/8	09-127	3/8	1 15/16

Collar Sets 1/2 Hole

No. 43-210 Set of 7 Collars. 3/4 to 1 1/8 diameter. Nos. 09-142, 09-143, 09-144, 09-145, 09-171, 09-172, 09-173. 1/2 Lb.

No. 43-211 Set of 6 Collars. 1 1/16 to 1 1/2 diameter. Nos. 09-141, 09-146, 09-147, 09-148, 09-174, 09-175. 1 Lb.

No. 43-212 Set of 6 Collars. 1 1/16 to 1 7/8 diameter. Nos. 09-149, 09-176, 09-177, 09-178, 09-179, 09-180. 1 1/2 Lbs.

No. 43-191 Set of 4 Collars for Sash Cutters. Nos. 09-140, 09-141, 09-150, 09-151. 1/2 Lb.

Cutter and Collar Sets — 1/2 Hole

No. 43-182 Standard Cutter Set. Consists of Cutters 09-100 to 09-109 inclusive and Collars 09-142 to 09-149 inclusive. Packed in wood box. 3 1/2 Lbs.

No. 43-213 Cove and Bead Cutter Set. Consists of Cutters 09-108, 09-127; 09-135 to 09-138 inclusive and collars 09-132 to 09-134. Packed with 43-345 Stub Spindle Assembly and SP-10 Wrench for H.D. Wood Shaper. 2 Lbs.

No. 43-214 Sash and Cabinet Cutter Set. Consists of Cutters 09-108, 09-120, 09-121, 09-123 to 09-128 inclusive and Collars 09-140, 09-141, 09-150 and 09-151. Packed with 43-345 Stub Spindle Assembly and SP-10 Wrench for H.D. Wood Shaper. 3 Lb.

Spacing Collars — 1/2, 3/4 and 1 Holes.

Cat. No. 1/2 Hole	Cat. No. 3/4 Hole	Cat. No. 1 Hole	Dia.	Thick-ness
09-133			13/16	1/8
09-150	43-250	43-310	1 1/8	13/16
09-155			3/4	
09-217	43-251		1 1/32	
09-134	43-252		1 1/32	1/4
09-140	43-253	43-313	1 1/16	
09-215	43-254	43-314	1 15/32	
09-151	43-255	43-315	1 1/8	
09-142			3/4	
09-171			13/16	
09-143			7/8	
09-172			15/16	3/8
09-144	43-256		1	
09-173	43-257		1 1/16	
09-145	43-258		1 1/8	
09-132	43-259		1 15/32	
09-141	43-260		1 1/16	
09-146	43-261	43-321	1 1/4	
09-174	43-262	43-322	1 1/16	
09-147	43-263	43-323	1 1/8	
09-175	43-264	43-324	1 1/16	
09-148	43-265	43-325	1 1/2	
	43-266	43-326	1 1/16	
09-177	43-267	43-327	1 1/8	
09-178	43-268	43-328	1 11/16	
09-149	43-269	43-329	1 1/4	
09-179	43-270	43-330	1 13/16	
09-180	43-271	43-331	1 1/8	

Collar Sets 3/4 and 1 Hole

No. 43-248 Set of 6 Collars. 3/4 hole, 1 1/16 to 1 1/2 diameter. Nos. 43-260, 43-261, 43-262, 43-263, 43-264, 43-265.

No. 43-249 Set of 6 Collars. 3/4 hole, 1 1/16 to 1 1/8 diameter. Nos. 43-266, 43-267, 43-268, 43-269, 43-270, 43-271.

No. 43-308 Set of 5 Collars. 1 hole, 1 1/4 to 1 1/2 diameter. Nos. 43-321, 43-322, 43-323, 43-324, 43-325.

No. 43-309 Set of 6 Collars. 1 hole, 1 1/16 to 1 1/8 diameter. Nos. 43-326, 43-327, 43-328, 43-329, 43-330, 43-331.

For Heavy Duty, Utility and 43-355 Wood Shapers


No. 43-344 3-Knife Safety Cutterhead. Enables circular saw moulding cutter to be used on the wood shaper. Includes wrench and bushing for use with 1/2 and 3/4 shaper spindles. Furnished without knives. 1 Lb.

For Heavy Duty, Utility and 43-355 Wood Shapers (continued)

No. 34-895 Auto-Set® Miter Gage. For straight and angle shaping. Has 3/8 x 3/4 x 18 guide bar and pivoting work support body with pointer and calibrations reading through 120° swing. Adjustable, positive stops at 90° and 45° positions. Accommodates No. 34-568 Clamp Attachment. 3 1/2 Lbs.

No. 34-568 Clamp Attachment for miter gage. Holds work evenly and safely when edge shaping with miter gage. Includes clamp bar, two sliding clamp screws, front and rear posts. 1 1/2 Lbs.


No. 34-873 Extra Clamp Screw and Bracket for clamp attachment. 1/2 Lb.




No. 43-186 Sliding Shaper Jig. For horizontal shaping operations such as tenon and groove cutting. Securely holds short and narrow work, prevents slipping. 15 Lbs.

For Two-Speed Heavy Duty Wood Shaper

No. 50-273 Mobile Base. For H.D. Shaper. 22 Lbs.



No. 43-348 Safety Ring Guard. For added safety and convenience on curved and circular edge shaping operations. Complete with mounting bracket. 9 Lbs.



No. 43-188 Sliding Shaper Jig. Provides greater cutting accuracy during a variety of shaping operations. Features three guide bar locations for positioning the workpiece as close as possible to both large and small diameter shaper cutters. Twelve mounting holes offer you a dozen options for moving the solid steel bars and cam-action clamps around the base in order to fit large and small workpieces, different machines and various types of operations. Not just for shapers, the Sliding Shaper Jig also helps you safely cut angled-tenons, tenons and dados on either left or right tilting table saws. 13 Lbs.


Delta Shaper Accessories (continued)

Door Edge Detail


All 2¹⁵/₁₆ diameter. 3/4 bore, 1/2 T-Bushing.




42-040




42-041




42-042



42-043



42-044



42-045

Flute or Half Round Convex

All 2¹⁵/₁₆ diameter. 3/4 bore, 1/2 T-Bushing.



42-073

Width	Cat. No.
1/4	42-070
3/8	42-071

Width	Cat. No.
1/2	42-072
3/4	42-073
1	42-074

Bead or Half Round Concave

All 2¹⁵/₁₆ diameter. 3/4 bore, 1/2 T-Bushing.



42-038

Width	Cat. No.
1/4	42-035
3/8	42-036

Width	Cat. No.
1/2	42-037
3/4	42-038
1	42-039


Corner Round

All 2¹⁵/₁₆ diameter. 3/4 bore, 1/2 T-Bushing.



42-090

1/4 and 1/2 Quarter Round




42-091

5/16 Quarter Round and 1/2 Cove



42-092

1/8 and 3/8 Quarter Round and 1/4 Bead



42-093

3/4 Quarter Round

Glue Joint

For cutting 1/2 to 1 1/4 Material. 2¹⁵/₁₆ dia. 3/4 bore, 1/2 T-Bushing.




42-052




42-052

Wedge Tongue and Groove

All 2¹⁵/₁₆ diameter. 3/4 bore, 1/2 T-Bushing.




42-054



42-053

Lock Miter Double Tongue and Groove

For cutting up to 1 1/8 material. 4 Diameter, 3/4 bore. Counterclockwise rotation only.



42-050




42-050

Delta Shaper Accessories (continued)


Male and Female Sash

All $2^{15}/16$ diameter. $3/4$ bore with $1/2$ T-Bushing.




Horizontal Panel Raising

For cutting $3/4$ material. With 15° shear for optimum cutting both with and across the grain. Use 42-120 Rub Bearing with $4^{1}/2$ Dia. Cutters and 42-121 Rub Bearing with 6 Dia. Cutter.



Face Cut	Dia.	Bore	Cat. No.
Convex	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-010
	6	$1^{1}/4$	42-020
Rd. Nose 17° Bevel	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-011
	6	$1^{1}/4$	42-021




Face Cut	Dia.	Bore	Cat. No.
Rd. Nose 18° Bevel	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-012
	6	$1^{1}/4$	42-022
Rd. Nose S-Cut	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-013
	6	$1^{1}/4$	42-023

Drawer Joint


All $2^{15}/16$ diameter. $3/4$ bore, $1/2$ T-Bushing.

Requires use of Stub Spindle. Counterclockwise rotation only.




Horizontal Panel Raising

For cutting $5/8$ material. With 15° shear for optimum cutting both with and across the grain. Use 42-120 Rub Bearing with $4^{1}/2$ Dia. Cutters and 42-121 Rub Bearing with 6 Dia. Cutter.




Face Cut	Dia.	Bore	Cat. No.
Convex	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-014
	6	$1^{1}/4$	42-024
Rd. Nose 17° Bevel	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-015
	6	$1^{1}/4$	42-025



Face Cut	Dia.	Bore	Cat. No.
Convex	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-016
	6	$1^{1}/4$	42-026
Rd. Nose 18° Bevel	$4^{1}/2$	$3/4$ with $1/2$ T-Bushing	42-017
	6	$1^{1}/4$	42-027

Straight

All $3/4$ bore with $1/2$ T-Bushing unless otherwise noted.




Width	Dia.	Cat. No.
$1/4$	$1^{11}/16$	42-104*
	$2^{2}/16$	42-108*
	$2^{15}/16$	42-060
$3/8$	$2^{15}/16$	42-061
	$1^{11}/16$	42-105*
$1/2$	$2^{2}/16$	42-109*
	$2^{15}/16$	42-062

Width	Dia.	Cat. No.
$3/4$	$2^{15}/16$	42-063
1	$2^{15}/16$	42-064
$1^{1}/2$	$2^{15}/16$	42-065

*Not supplied with $1/2$ T-Bushing

Horizontal Panel Raising/Back Cutters

With 15° for optimum cutting both with and across the grain. Includes $1/4$ tongue spacer. For use with $4^{1}/2$ dia. horizontal panel raising cutters to cut $3/4$ material. $3/8$ diameter. $3/4$ bore with $1/2$ T-Bushing.



Delta Shaper Accessories (continued)


Double Sided 8-Cutter Cope and Pattern Set

Includes $\frac{1}{4}$ and $\frac{1}{2}$ wide x $\frac{5}{8}$ tongue and groove cutters. All $2\frac{15}{16}$ diameter unless otherwise noted. $\frac{3}{4}$ bore. For use with 42-122 rub bearing. For cutting $1\frac{3}{8}$ passage doors and $1\frac{1}{4}$ entry doors.

Cat. No. 42-000 Set Includes

Cat. No.	Description
42-100	Rail for Concave Stile
42-101	Rail for Concave Stile
42-102	Concave Stile ($2\frac{11}{16}$ Dia.)
42-103	Concave Stile ($2\frac{11}{16}$ Dia.)
42-104	$\frac{1}{4}$ x $1\frac{11}{16}$ Dia. Straight (Tongue)
42-105	$\frac{1}{2}$ x $1\frac{11}{16}$ Dia. Straight (Tongue)
42-060	$\frac{1}{4}$ x $2\frac{15}{16}$ Dia. Straight (Groove)
42-062	$\frac{1}{2}$ x $2\frac{15}{16}$ Dia. Straight (Groove)

Cutters available separately.



Ball Bearing Rub Collars

For use with carbide-tipped cope and pattern cutter sets and horizontal panel raising cutters.

Cat. No.	Diameter	Bore	Use With Cutter and/or Sets
42-120	$1\frac{3}{8}$	$\frac{3}{4}$	42-010 to 42-017, 42-030 and 42-031
42-121	3	$1\frac{1}{4}$	42-020 to 42-027
42-122	$1\frac{11}{16}$	$\frac{3}{4}$	42-000
42-123	$2\frac{1}{16}$	$\frac{3}{4}$	42-001 to 42-003

T-Bushings

Set of two. For changing bore diameters on individual carbide tipped cutters and cutter sets.

Cat. No.	Bore Change	Use With
42-125	$1\frac{1}{4}$ to 1	Single Cutters
42-126	$\frac{3}{4}$ to $\frac{1}{2}$	3 to 6-Piece Cutter Sets*
42-127	$\frac{3}{4}$ to $\frac{1}{2}$	Single Cutters

*Includes 1 long and 1 short T-Bushing

6 Cutter Cope and Pattern Sets

Includes $\frac{1}{4}$ wide x $\frac{3}{8}$ tongue and groove cutters. All $2\frac{15}{16}$ diameter unless otherwise noted. $\frac{3}{4}$ bore with $\frac{1}{2}$ T-Bushing. For use with 42-123 rub bearing. Cutters available separately.

For cope and pattern cutting $\frac{3}{4}$ to $1\frac{1}{8}$ material



For cope and pattern cutting $\frac{3}{4}$ to $1\frac{1}{8}$ material



For cope and pattern cutting $\frac{3}{4}$ to $1\frac{1}{8}$ material



For glass panel cutting $\frac{3}{4}$ to 1 material



For glass panel cutting $\frac{3}{4}$ to 1 material



For glass panel cutting $\frac{3}{4}$ to 1 material



For tongue and groove cutting $\frac{3}{4}$ material



For tongue and groove cutting $\frac{3}{4}$ material



For tongue and groove cutting $\frac{3}{4}$ material



Cat. No. 42-001 Set Includes

Cat. No.	Description
42-106	Rail for Concave Stile
42-107	Concave Stile ($2\frac{11}{16}$ Dia.)
42-108	$\frac{1}{4}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-109	$\frac{1}{2}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-060	$\frac{1}{4}$ x $2\frac{15}{16}$ Dia. Straight (Groove)
42-062	$\frac{1}{2}$ x $2\frac{15}{16}$ Dia. Straight (Groove)

Cat. No. 42-002 Set Includes

Cat. No.	Description
42-110	Rail for Ogee Stile
42-111	Ogee Stile
42-108	$\frac{1}{4}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-109	$\frac{1}{2}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-060	$\frac{1}{4}$ x $2\frac{15}{16}$ Dia. Straight (Groove)
42-062	$\frac{1}{2}$ x $2\frac{15}{16}$ Dia. Straight (Groove)

Cat. No. 42-003 Set Includes

Cat. No.	Description
42-114	Rail for Ovolo Stile
42-115	Ovolo Stile
42-108	$\frac{1}{4}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-109	$\frac{1}{2}$ x $2\frac{3}{16}$ Dia. Straight (Tongue)
42-060	$\frac{1}{4}$ x $2\frac{15}{16}$ Dia. Straight (Groove)
42-062	$\frac{1}{2}$ x $2\frac{15}{16}$ Dia. Straight (Groove)



PARTS, SERVICE OR WARRANTY ASSISTANCE

All Delta Machines and accessories are manufactured to high quality standards and are serviced by a network of factory service centers and authorized service stations listed in your owner's manual. To obtain additional infor-

mation regarding your Delta quality product or to obtain parts, service or warranty assistance, please call or fax Delta's toll-free 'hotline' number.

Delta maintains a modern, efficient Parts Distribution Center, maintaining an inventory of over 15,000 parts located in Memphis, Tennessee.

Highly qualified and experienced Customer Service Representatives are standing by to assist you on weekdays from 7:00 A.M. to 6:00 P.M. Memphis time.



Memphis, TN 38118
4290 Raines Road
Phone: (901) 363-8800

HOTLINE
800-223-PART
FAX: 800-535-6488



Delta Building Trades and Home Shop Machinery Two Year Limited Warranty

Delta will repair or replace, at its expense and at its option, any Delta machine, machine part, or machine accessory which in normal use has proven to be defective in workmanship or material, provided that the customer returns the product prepaid to a Delta factory service center or authorized service station with proof of purchase of the product within two years and provides Delta with reasonable opportunity to verify the alleged defect by inspection. Delta may require that electric motors be returned prepaid to a motor manufacturer's authorized station for inspection and repair or replacement. Delta will not be responsible for any asserted defect which has resulted from normal wear, misuse, abuse or repair or alteration made or specifically authorized by anyone other than an authorized Delta Service facility or representative. Under no circumstances will Delta be liable for incidental or consequential damages resulting from defective products. This warranty is Delta's sole warranty and sets forth the customer's exclusive remedy, with respect to defective products; all other warranties, express or implied, whether of merchantability, fitness for purpose, or otherwise, are expressly disclaimed by Delta.