



Replacement Parts

Ref. No.	Part No.	Description	Ref. No.	Part No.	Description
1	Cannot Furnish	Nameplate	25	904-10-031-2097	29/64" Steel Washer
2	Cannot Furnish	Lathe Bed, with Nameplate	26	434-01-022-0001	Center Point
3	901-06-450-2252	#2 X 3/16" Drive Screw	27	904-07-011-5711	Fiber Washer
4	928-01-021-3378	Coil Spring	28	Cannot Furnish	Tailstock Quill
5	434-01-022-0010	Center Point	29	Cannot Furnish	Quill Adj. Screw
6	904-07-010-5565	Fiber Washer	30	434-01-072-0020	Clamp Plate
7	Cannot Furnish	Spindle #1 Morse Taper	31	Cannot Furnish	3/8"-16 Hex Nut, L.H.
8	Cannot Furnish	Headstock Pulley	32	Cannot Furnish	Spec. 3/8"-16 Hexagon Nut
9	Cannot Furnish	Headstock Ass'y., Incl:	33	Cannot Furnish	Tailstock Body
9	Cannot Furnish	Headstock	34	Cannot Furnish	Lock Bolt, 3/8-16 X 1-1/2", with Ball-End Handle
10	Cannot Furnish	Steel Plate	35	Cannot Furnish	Cup Center, #1 Morse Taper Shank, with Center Point
11	Cannot Furnish	Index Pin	36	901-11-020-0839	7/16-14 X 2" Carriage Bolt
12	Cannot Furnish	Ball Bearing	37	902-09-040-5914	7/16-14 Hex Cap Nut
13	Cannot Furnish	Drive Center	38	904-10-031-2097	29/64" Steel Washer
14	Cannot Furnish	3" Face Plate	39	928-01-021-3377	Coil Spring
15	921-01-010-0028	1/4" Steel Ball	40	434-01-072-0020	Clamp Plate
16	901-04-190-0201	5/16-18 X 5/16" Hex Soc. Set Scr.	41	Cannot Furnish	Body for Tool Rest Base
17	901-04-190-0253	1/4-28 X 1/4" Hex Soc. Set Scr.	42	434-01-072-0018	Support Plate
18	901-02-010-0551	#10-32 X 1/4" Rd. Hd. Scr.	43	418-01-412-0001	Lock Bolt
19	904-01-010-1605	3/8" Steel Washer	44	46-692	12" Tool Rest
20	Cannot Furnish	3/8-16 X 4" Hex Hd. Scr.	45	901-11-020-0839	7/16-14 X 2" Carriage Bolt
21	Cannot Furnish	3/8-16 X 3-1/4" Hex Hd. Scr.	46	Cannot Furnish	1/8" Hex Wrench
22	930-05-991-3515	Ball Crank Ass'y., Incl:	47	Cannot Furnish	5/32" Hex Wrench
23	901-04-190-0201	5/16-18 X 5/16" Soc. Set Scr.	48	Cannot Furnish	3/4" Hex Box Wrench
24	902-09-040-5914	11/16"-14 Hex Cap Nut	49	434-01-101-0002	1-1/4" Open End Wrench

ACCESSORIES

46-121	1" Wood Turning Skew Chisel, with Handle
46-122	3/4" Wood Turning Gouge Chisel, with Handle
46-123	1/4" Wood Turning Gouge Chisel, with Handle
46-124	1/2" Wood Turning Skew Chisel, with Handle
46-125	1/8" Wood Turning Parting Tool, with Handle
46-126	1/2" Wood Turning Gouge Chisel, with Handle
46-127	1/2" Wood Turning Spear Point Chisel, with Handle
46-128	1/2" Wood Turning Round Nose Chisel, with Handle
46-130	Set of Eight Wood Turning Lathe Chisels
46-690	4" Tool Rest
46-692	12" Tool Rest
46-694	24" Tool Rest
46-695	Right Angle Tool Rest
46-697	Floor Stand for Tool Rest
46-801	1/8" Sq. Nose Tungsten Alloy Tipped Lathe Chisel
46-802	1/8" Round Nose Tungsten Alloy Tipped Lathe Chisel
46-803	1/4" Sq. Nose Tungsten Alloy Tipped Lathe Chisel
46-804	1/4" Round Nose Tungsten Alloy Tipped Lathe Chisel
46-815	Twelve Coarse Garnet Paper Disks, 8-3/8" Dia., #40 Grit
46-817	Twelve Fine Garnet Paper Disks, 8-3/8" Dia., #80 Grit
Cannot Furnish	#1 M. T. Arbor with Jacobs Chuck and Hex Wrench
Cannot Furnish	8-1/2" Sanding Disc
Cannot Furnish	Sanding Table
Cannot Furnish	Steady Rest